Metrohm

1   Purpose

This document describes new functions, changes, improvements and fixed bugs in the following firmware version:

- 57.1027.0005 for OS version 007

in comparison with the firmware version:

- 57.1027.0004 for OS version 007

2   New functions

The following new functions have been integrated:

- None

3   Improvements

The following improvements were made:

- Various improvements regarding the drive and blocking of the piston implemented.
- Various optimizations regarding stability.

4   Fixed bugs

The following bugs were fixed:

- Default settings of the statistics changed (TITR-19062).
- Drift value for calculation of automatic drift correction was not found (TITR-21473).
- After deleting a titer, a new mean value was saved (TITR-21450).
- Freezing of the buret after reaching the end volume (TITR-21931).
- Freezing of the instrument when printing after titer determination (TITR-21983).

5 Known bugs

The following bugs are known:

- After restart, the mean values on the result screens are rounded upwards.
- Instrument freezes during sample data retrieval (TITR-22017).