

1 Purpose

This document describes new functions, the changes, improvements and fixed bugs and problems in the following firmware version:

- 57.1008.0014 for OS version 006
- in comparison with the firmware version:
- 57.1008.0013 for OS version 005

2 New functions

The following new functions have been integrated:

- Mettler Toledo balances with COM port are supported
- Measuring point list as CSV file (TITR-18026)

3 Improvements

The following improvements were made:

- Optimizations on the GUI

4 Fixed bugs

The following bugs and problems were fixed:

- Warning message after calibration (TITR-18057).
- MIM variable is not correctly displayed (TITR-16939).
- Problem with the calculation with EP and FP1 (TITR-18059).
- Problem with the dosing rate (TITR-17823).
- The method is changed when a method is executed (TITR-17675, TITR-17347).
- Titration mode pH-MEAS initial measured value implemented (TITR-17265)

5 Known bugs and problems

The following bugs or problems are known:

