

1 Purpose

This document describes new functions, changes, improvements and fixed bugs in the following firmware version:

- 57.1027.0007 for OS version 007

In comparison with the firmware version:

- 57.1027.0005 for OS version 007

2 New functions

The following new functions have been integrated:

- None

3 Improvements

The following improvements were made:

- After restart, the mean values on the result screens are no longer rounded upwards.
- Various improvements.

4 Fixed bugs

The following bugs were fixed:

- Weight data could not be received (TITR-20288).
- Eco KF Conditioning (TITR-22156).
- Strange behavior of the printer (TITR-22357).
- After a titer was deleted from the statistics, it is nonetheless still highlighted in the next series (TITR-22439).
- Missing sample ID in the PDF report (TITR-22861).
- Instrument freezes and stirrer does not work correctly (TITR-23568).
- Instrument crashes during use (TITR-23624).
- Instrument freezes during refilling (TITR-23832).
- Miscellaneous problems (TITR-23919).
- Error in titer (TITR-24060).
- Error in firmware (TITR-24144).

5 Known bugs

The following bugs are known:

- None