

## 1 Purpose

This document describes new functions, changes, improvements and fixed bugs in the following firmware version:

- 57.1027.0008 for OS version 008

In comparison with the firmware version:

- 57.1027.0007 for OS version 007

## 2 New functions

The following new functions have been integrated:

- Initial adjustment for servo motor at time of device production
- Detection of main board version in relation to initial adjustment

## 3 Improvements

The following improvements were made:

- Optimizations for tests in production (OS version 008).

## 4 Fixed bugs

The following bugs were fixed:

- Instrument freezes during sample data request (TITR-22017).
- After restart, the mean values on the result screens are rounded upwards (Defect 97966).

## 5 Known issues

The following bugs are known:

- None