

1 Purpose

This document describes new functions, changes, and improvements in the following firmware version:

- 57.1027.0010 for OS version 008

In comparison with the firmware version:

- 57.1027.0009 for OS version 008

2 New functions

The following new functions have been integrated:

- Various new functions for service and production.

3 Improvements

The following improvements were made:

- The MAC address is now displayed in **System ► About...** (TITR-28395).

4 Fixed bugs

The following bugs were fixed:

- The system freezes at the end of the **Switch cylinder unit**.
- The system freezes as soon as the user presses the **[Start]** key in the **Live status** screen (when Conditioning = off and Sample addition time = 0).
- If the Ethernet cable is not connected, then the message **Connect network cable** appears continuously.
- The message **Network is being configured...** does not appear after the Ethernet cable has been connected.
- After the first restart of the device, the subnet mask, gateway, and IP address are not printed in the system report.
- If the user prints the **Report from method** after the titration has been completed (with all reports and PC/LIMS = on), then the colons are not printed for the duration of determination (hh:mm:ss).

