

1 Purpose

This document describes new functions, changes, improvements and fixed bugs in the following firmware version:

- 57.1027.0004 for OS version 007

in comparison with the firmware version:

- 57.1027.0003 for OS version 006

2 New functions

The following new functions have been integrated:

- None

3 Improvements

The following improvements were made:

- PDF reports can be configured more flexibly.
- PDF report timing has improved

4 Fixed bugs

The following bugs were fixed:

- The new titer is not used after the titer determination (TITR-19927).
- Problems with the SMN calculation (TITR-20132).
- Bug during electrode testing **Electrode defective 011-002** (TITR-18630).
- The print report is always 5 pages long (TITR-20151).

5 Known bugs

The following bugs are known:

- None